





















# **KINGLEAD AUTO PARTS**












Water Pump Catalogue 2007






 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> 16100-79165</p> <p><b>WP-01</b></p>	 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-12A 16100-39116</p> <p><b>WP-02</b></p>
 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-19A 16100-61010</p> <p><b>WP-03</b></p>	 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-22AG=GWT-22A 16100-61041/0</p> <p><b>WP-04</b></p>
 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-30A 16100-19015/6/7</p> <p><b>WP-05</b></p>	 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-48A 16100-59085</p> <p><b>WP-06</b></p>
 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-50A 16100-19055</p> <p><b>WP-07</b></p>	 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-54A 16100-79035/6</p> <p><b>WP-08</b></p>
 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-57A 16100-69085 16100-69275</p> <p><b>WP-09</b></p>	 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-58A 16100-01010</p> <p><b>WP-10</b></p>











 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-59A 16100-19075/6/7</p> <p><b>WP-11</b></p>	 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-60A 16100-19045</p> <p><b>WP-12</b></p>
 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-61A 16100-59137/6/5</p> <p><b>WP-13</b></p>	 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-64A 16100-39345</p> <p><b>WP-14</b></p>
 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-68A 16100-19055</p> <p><b>WP-15</b></p>	 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-77A 16110-79025</p> <p><b>WP-16</b></p>
 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-81A 16100-69225</p> <p><b>WP-17</b></p>	 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-83A 16110-19135 16110-19145</p> <p><b>WP-18</b></p>
 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-85A 16100-79155</p> <p><b>WP-19</b></p>	 <p><b>Application:</b> TOYOTA</p> <p><b>Replace NO:</b> GWT-90A 16100-69345</p> <p><b>WP-20</b></p>





 <p><b>Application:</b> <b>TOYOTA</b></p> <p><b>Replace NO:</b> GWT-71A 16100-69205</p> <p><b>WP-21</b></p>	 <p><b>Application:</b> <b>HONDA</b></p> <p><b>Replace NO:</b> 19200-PTO-003</p> <p><b>WP-22</b></p>
 <p><b>Application:</b> <b>HONDA</b></p> <p><b>Replace NO:</b> 19200-PEO-010</p> <p><b>WP-23</b></p>	 <p><b>Application:</b> <b>HONDA</b></p> <p><b>Replace NO:</b> 19200-P08-004</p> <p><b>WP-24</b></p>
 <p><b>Application:</b> <b>OPEL</b></p> <p><b>Replace NO:</b></p> <p><b>WP-25</b></p>	 <p><b>Application:</b> <b>OPEL</b></p> <p><b>Replace NO:</b> GWO-11A 1334014 90284913</p> <p><b>WP-26</b></p>
 <p><b>Application:</b> <b>OPEL</b></p> <p><b>Replace NO:</b> GWO-10A 1334008 90220568</p> <p><b>WP-27</b></p>	 <p><b>Application:</b> <b>LADA</b></p> <p><b>Replace NO:</b> 2108-1307010</p> <p><b>WP-28</b></p>
 <p><b>Application:</b> <b>LADA</b></p> <p><b>Replace NO:</b> 2112-1307010</p> <p><b>WP-29</b></p>	 <p><b>Application:</b> <b>LADA</b></p> <p><b>Replace NO:</b> 3A3-1102 (245-13070107)</p> <p><b>WP-30</b></p>











 <p><b>WP-31</b></p>	<p><b>Application:</b> LADA</p> <p><b>Replace NO:</b> 2101-1307010 4197598</p>	 <p><b>WP-32</b></p>	<p><b>Application:</b> AUDI</p> <p><b>Replace NO:</b> 078.121.004L 078.121.004R 078.121.006A</p>
 <p><b>WP-33</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-01A 21010-13200/1/2</p>	 <p><b>WP-34</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-05A 21010-E3000/1/3/4 21010-P7525/6/7/8/9 21010-V0725/6 21010-W3685</p>
 <p><b>WP-35</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-19A 21010-09W25 21010-31W25/6</p>	 <p><b>WP-36</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-20A 21010-D0125/6</p>
 <p><b>WP-37</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-21A 21010-C6025/6</p>	 <p><b>WP-38</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-23AF 21010-G3925/6 21010-N5825/6/7 21010-N5828/9</p>
 <p><b>WP-39</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-24A 21010-01M01/0 21010-01M25 21010-50A25/6/7</p>	 <p><b>WP-40</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-37A 21010-10G25 21010-10G26</p>

 <p><b>WP-41</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-39A 21010-77A00</p>	 <p><b>WP-42</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-41A 21010-12G25/6</p>
 <p><b>WP-43</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-42A 21010-53Y00</p>	 <p><b>WP-44</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-53A 21010-61504/5 21010-61526/7/8/9 21010-61585</p>
 <p><b>WP-45</b></p>	<p><b>Application:</b> NISSAN</p> <p><b>Replace NO:</b> GWN-54A 21010-85G25/6</p>	 <p><b>WP-46</b></p>	<p><b>Application:</b> MAZDA</p> <p><b>Replace NO:</b> GWMZ-02A 0305-15-010 0305-99-151 0305-15-010D/E</p>
 <p><b>WP-47</b></p>	<p><b>Application:</b> MAZDA</p> <p><b>Replace NO:</b> GWMZ-21A E-301-15-010A/D E5B6-15-010A</p>	 <p><b>WP-48</b></p>	<p><b>Application:</b> MAZDA</p> <p><b>Replace NO:</b> GWMZ-29A FE79-15-010B/C 8AG1-15-010A/B</p>
 <p><b>WP-49</b></p>	<p><b>Application:</b> MAZDA</p> <p><b>Replace NO:</b> GWMZ-30A RF01-99-154</p>	 <p><b>WP-50</b></p>	<p><b>Application:</b> MAZDA</p> <p><b>Replace NO:</b> GWMZ-31A B630-15-010 8AB3-15-010 8AB4-15-010</p>

 <p><b>WP-51</b></p>	<p><b>Application:</b> MAZDA</p> <p><b>Replace NO:</b> GWMZ-32A 8AH2-15-010 8AH2-15-010A/B</p>	 <p><b>WP-52</b></p>	<p><b>Application:</b> MAZDA</p> <p><b>Replace NO:</b> GWMZ-37A ZZM1-15-010</p>
 <p><b>WP-53</b></p>	<p><b>Application:</b> MAZDA</p> <p><b>Replace NO:</b> GWMZ-38A 8AL1-15-010B</p>	 <p><b>WP-54</b></p>	<p><b>Application:</b> MAZDA</p> <p><b>Replace NO:</b> GWMZ-40A 8AW4-15-100A</p>
 <p><b>WP-55</b></p>	<p><b>Application:</b> MAZDA</p> <p><b>Replace NO:</b> GWMZ-41A 8AG9-15-010</p>	 <p><b>WP-56</b></p>	<p><b>Application:</b></p> <p><b>Replace NO:</b> GWF-53A E69Z-8501A</p>
 <p><b>WP-57</b></p>	<p><b>Application:</b> MITSUBISHI</p> <p><b>Replace NO:</b> GWM-17A MD030863</p>	 <p><b>WP-58</b></p>	<p><b>Application:</b> MITSUBISHI</p> <p><b>Replace NO:</b> GWM-23A MD041041 MD997079 MD997080</p>
 <p><b>WP-59</b></p>	<p><b>Application:</b> MITSUBISHI</p> <p><b>Replace NO:</b> GWM-26A MD025475</p>	 <p><b>WP-60</b></p>	<p><b>Application:</b> MITSUBISHI</p> <p><b>Replace NO:</b> GWM-33A ME015045</p>

 <p><b>WP-61</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            GWM-37A            MD997178            MD997157            MD997158</p>	 <p><b>WP-62</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            4DR5</p>
 <p><b>WP-63</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            GWM-13A            MD021490            MD997082            MD997158</p>	 <p><b>WP-64</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            GWM-02A            K435080            MD011300</p>
 <p><b>WP-65</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            GWM-39A            MD664616</p>	 <p><b>WP-66</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            GWM-40A            MD997244            MD980000</p>
 <p><b>WP-67</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            GWM-44A            MD997147            MD972052            MD997621</p>	 <p><b>WP-68</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            GWM-45A            MD972053</p>
 <p><b>WP-69</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            GWM-47A            MD300799            MD179030            MD306414</p>	 <p><b>WP-70</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            GWM-54A            MD323372</p>

 <p><b>WP-71</b></p>	<p><b>Application:</b>  <b>mitsubishi</b></p> <p><b>Replace NO:</b>            ME995426</p>	 <p><b>WP-72</b></p>	<p><b>Application:</b>  <b>ISUZU</b></p> <p><b>Replace NO:</b>            GWIS-01A            8-94202-477-1            8-94224-894-0</p>
 <p><b>WP-73</b></p>	<p><b>Application:</b>  <b>ISUZU</b></p> <p><b>Replace NO:</b>            GWIS-13A            8-94379-864-0            9-13610-122-0            9-13610-164-0</p>	 <p><b>WP-74</b></p>	<p><b>Application:</b>  <b>ISUZU</b></p> <p><b>Replace NO:</b>            GWIS-16A            5-13610-187-0</p>
 <p><b>WP-75</b></p>	<p><b>Application:</b>  <b>ISUZU</b></p> <p><b>Replace NO:</b>            GWIS-22A            8-94146-326-0            8-94332-637-0            8-94376-846-0</p>	 <p><b>WP-76</b></p>	<p><b>Application:</b>  <b>ISUZU</b></p> <p><b>Replace NO:</b>            GWIS-25A            8-94140-341-2</p>
 <p><b>WP-77</b></p>	<p><b>Application:</b>  <b>ISUZU</b></p> <p><b>Replace NO:</b>            GWIS-26A            8-94232-082-1            8-94332-920-0</p>	 <p><b>WP-78</b></p>	<p><b>Application:</b>  <b>ISUZU</b></p> <p><b>Replace NO:</b>            GWIS-29A            8-94155065-0            8-94376850-0</p>
 <p><b>WP-79</b></p>	<p><b>Application:</b>  <b>ISUZU</b></p> <p><b>Replace NO:</b>            GWIS-31A            8-94332-638-0            8-94376-847-0            8-94174-226-2            8-97021-774-0</p>	 <p><b>WP-80</b></p>	<p><b>Application:</b>  <b>ISUZU</b></p> <p><b>Replace NO:</b>            GWIS-34A            8-97125-975-Z            8-97061-280-Z</p>

 <p><b>WP-81</b></p>	<p><b>Application:</b></p> <p><b>Replace NO:</b> 050.121.010A 050.121.010AV 050.121.010AX</p>	 <p><b>WP-82</b></p>	<p><b>Application:</b> SANTANA</p> <p><b>Replace NO:</b> 06A-121-021 2000GSI</p>
 <p><b>WP-83</b></p>	<p><b>Application:</b> SANTANA</p> <p><b>Replace NO:</b> GWVW-07A 026-121-005A/C</p>	 <p><b>WP-84</b></p>	<p><b>Application:</b> SUZUKI</p> <p><b>Replace NO:</b> GWS-11A 17400-78830</p>
 <p><b>WP-85</b></p>	<p><b>Application:</b> SUZUKI</p> <p><b>Replace NO:</b> GWS-14A 17400-70D00</p>	 <p><b>WP-86</b></p>	<p><b>Application:</b> SUZUKI</p> <p><b>Replace NO:</b> GWS-15A 17400-82820</p>
 <p><b>WP-87</b></p>	<p><b>Application:</b> SUZUKI</p> <p><b>Replace NO:</b> GWS-16A 17400-60811/2</p>	 <p><b>WP-88</b></p>	<p><b>Application:</b> DAIHATSU</p> <p><b>Replace NO:</b> GWD-17A 16100-87787</p>
 <p><b>WP-89</b></p>	<p><b>Application:</b> DAIHATSU</p> <p><b>Replace NO:</b> GWD-32A 16100-87182</p>	 <p><b>WP-90</b></p>	<p><b>Application:</b> DAIHATSU</p> <p><b>Replace NO:</b> PA841 16110-15070 16110-15080 16110-19075 16110-19085 16110-19086</p>

